

Photographs from Site Inspection
Report dated 11/19/87

9832933



PG 1 OF 5

NO. 3



PHOTOGRAPHER/WITNESS

11-12-87 / 14:34 / south

DATE / TIME / DIRECTION

COMMENTS

view south of trash
pile*cc Robt. [signature]*

PHOTOGRAPHER/WITNESS

11-12-87 / 14:32 / SOUTH

DATE / TIME / DIRECTION

COMMENTS

view of trash pile

cc Robt. [signature]

NO.

2

Photographer / Witness

W. Robert [Signature]

TXD981517691

Date / Time / Direction

11-12-87/14:37/WEST

Comments: PAN VIEW OF EAST
BOUNDRY OF SITE



PANAROMA VIEW CONTINUED ON 2B OF 5



Anthony R. Hall

Date / Time / Direction

11-12-87/14:37/WEST

Comments: PAN VIEW OF EAST

BOUNDRY OF SITE



PANAROMA VIEW CONTINUED ON 2A OF 5

TXD981517691

NO.

10



PHOTOGRAPHER/WITNESS

W. Kelly

DATE / TIME / DIRECTION

11-12-87/15:04/NORTH

COMMENTS

VIEW OF TIRES

PHOTOGRAPHER/WITNESS

W. Kelly

DATE / TIME / DIRECTION

11-12-87/15:01/SOUTH

COMMENTS

VIEW OF TRASH PILE



NO.

8

TXD981517691

NO

14



PHOTOGRAPHER/WITNESS

DATE / TIME / DIRECTION

11-12-87/15:10/SOUTH

COMMENTS

VIEW OF TIRES

PHOTOGRAPHER/WITNESS

DATE / TIME / DIRECTION

11-12-87/15:11/SOUTH

COMMENTS

VIEW OF TIRES



NO.

12

TXD981517691

NO.

18



PHOTOGRAPHER/WITNESS

W. Kelly [Signature]

DATE / TIME / DIRECTION

11-12-87/15:22/NORTHWEST

COMMENTS

VIEW OF NORTHEAST
CORNER/BOUNDRY OF SITE

PHOTOGRAPHER/WITNESS

W. Kelly [Signature]

DATE / TIME / DIRECTION

11-12-87/15:22/SOUTHEAST

COMMENTS

VIEW OF EASTERN
BOUNDRY OF SITE



NO.

19